Scope of	Work for Property Loc	cated	at:		<u>90</u>	4 West Hadley Street	
	Property is: Single Fam	nily	1	Duple	х 🗆	Other	
Date:	9/2/2014						
ake no respo		after the	e insp	ection da	ite, or f	City of Milwaukee, the Redevelopment Authority, and their reor or omissions through error or oversight. The list does not neel lock Grant or HOME programs.	
Exterior	Condition Report						
Location Site	Required Work Landscaping	n/a		Yes ⊡		te/Comments f Help \$	Cost 700.00
	Steps/Handrails	n/a		Yes 🗹	ser	vice steps \$	900.00
	Service walks	n/a	1	Yes [	]	\$	
	Fencing	n/a	7	Yes 🗆	]	\$	
	Parking	n/a		Yes 🖸	dri	veway \$	2,800.00
	Retaining walls	n/a		Yes 🗸		\$	900.00
	Other	n/a		Yes [	]	\$	_
	Other	n/a		Yes [	]	\$	
Garage	Singles: repair	n/a	7	Yes [	]	\$	
	Shingles: Roof over existing	n/a	7	Yes [	]	\$	_
	Shingles:Tear off & re-roof	n/a		Yes 🗸	]	\$	4,500.00
	Gutters/downspouts	n/a	7	Yes [	]	\$	
	Flashing	n/a	7	Yes [	]	\$	
	Eaves	n/a		Yes 🔽	]	\$	400.00
	Siding	n/a	7	Yes [	]	\$	
	Doors	n/a		Yes 🗸	]	\$	900.00
	Windows	n/a	<b>V</b>	Yes [	]	\$	
	Slab	n/a	<b>V</b>	Yes [	]	\$	
	Paint	n/a		Yes 🗸	]	\$	800.00
	Electrical	n/a	<b>V</b>	Yes [	]	\$	
	Other	n/a		Yes [	]	\$	
Porches	Roof	n/a	7	Yes [	]	\$	
	Deck-upper	n/a		Yes 🗹	]	\$	2,880.00
	Decklower	n/a		Yes 🗹	]	\$	1,680.00
	Steps/handrails	n/a	7	Yes [	]	\$	
	Ceiling	n/a	1	Yes [	]	\$	
	Guardrails	n/a	1	Yes [	]	\$	
	Other	n/a		Yes 🗹	pei	mit \$	85.00
	Paint	n/a	П	Yes 🗸	1	\$	800.00

n/a 🗌 Yes 🗹 rear porch

Other

\$

2,500.00

## House

Chimney	n/a ☐ Yes ☑	\$ 450.00
Shingles: repair	n/a ☑ Yes 🗌	\$
Shingles: Roof over existing	n/a ☑ Yes 🗌	\$
Shingles:Tear off & re-roof	n/a ☐ Yes ☑	\$ 11,000.00
Gutters/downspouts	n/a ☐ Yes ☑	\$ 1,008.00
Flashing	n/a ☑ Yes 🗌	\$
Eaves	n/a ☐ Yes ☑	\$ 600.00
Siding	n/a ☑ Yes 🗌	\$
Storm Doors	n/a ☑ Yes 🗌	\$
Prime ("main") Doors	n/a ☐ Yes ☑	\$ 1,400.00
Storm Windows	n/a ☑ Yes 🗌	\$
Prime ("main") Windows	n/a ☐ Yes ☑	\$ 5,270.00
Paint	n/a ☐ Yes ☑	\$ 3,500.00
Foundation	n/a ☐ Yes ☑	\$ 10,500.00
Electrical	n/a ☑ Yes 🗌	\$
Other	n/a ☐ Yes ☑ window screens	\$ 425.00
Other	n/a 🗌 Yes 🗹 <b>basement windows</b>	\$ 2,400.00
Other	n/a ☐ Yes ☐	\$
Other	n/a ☐ Yes ☐	\$

Exterior: Estimated Cost:\* \$ 56,398.00

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Co	ondition Report Unit: Entire unit (single family)	<b>√</b>		Lower unit of duplex	
Mechanical Heating	Upper unit of duplex Required Work			Other	
J	Repair/replace boiler	n/a ✓	Yes 🗌		\$
	Repair radiation	n/a ☑	Yes 🗌		\$
	Repair/replace furnace	n/a 🗌	Yes 🗸		\$ 3,080.00
	Repair ductwork	n/a 🗌	Yes 🗸		\$ 1,800.00
	Replace thermostat	n/a 🗌	Yes 🗸		\$ 100.00
	Repair/replace grilles	n/a 🗌	Yes 🗸		\$ 200.00
Electrical	Other	n/a 🗌	Yes 🗸	permit	\$ 85.00
Electrical	Repair/replace receptacles	n/a 🗌	Yes ✓		\$ 2,900.00
	Repair/replace switches	n/a 🗌	Yes ✓		\$ 2,500.00
	Repair/replace fixtures	n/a 🗌	Yes ✓		\$ 2,700.00
	Install outlets and circuits	n/a ☑	Yes 🗌		\$
	Install outlets and circuits	n/a ✓	Yes 🗌		\$
	Install outlets and circuits	n/a ✓	Yes 🗌		\$
	Install outlets and circuits	n/a ✓	Yes 🗌		\$
	Upgrade service	n/a 🗌	Yes 🗸		\$ 1,749.00
	Other	n/a 🗌	Yes 🗸	permit	\$ 85.00
Dlumbing	Other	n/a 🗌	Yes 🗌		\$
Plumbing	Repair/replace kitchen sink	n/a 🗌	Yes 🗌		\$
	Repair/replace kitchen sink fauce	in/a □	Yes 🗌		\$
	Repair/replace tub	n/a 🗌	Yes 🗌		\$ 
	Repair/replace tub faucet	n/a 🗌	Yes 🗌		\$
	Repair/replace toilet	n/a 🗌	Yes 🗌		\$
	Repair/replace lavatory	n/a 🗌	Yes 🗌		\$
	Repair/replace lavatory faucet	n/a 🗌	Yes 🗌		\$
	Repair/replace wash tub	n/a 🗌	Yes 🗌		\$
	Repair/replace wash tub faucet	n/a 🗌	Yes 🗌		\$
	Other	n/a 🗌	Yes 🗸	permit	\$ 85.00
	Repair drain/waste/vent piping	n/a 🗌	Yes 🗸		\$ 2,500.00
	Repair water piping	n/a 🗌	Yes ✓		\$ 2,500.00
	Repair/replace water heater	n/a 🗌	Yes 🗸		\$ 1,300.00
	Other	n/a 🗌	Yes 🗸	complete kitchen	\$ 1,455.00

n/a 🗌 Yes 🗹 complete bathroom (2)

Other

\$

4,340.00

Windows							
	Replace broken glass	n/a	J	Yes			\$
	Repair or replace sash	n/a	J	Yes			\$
Doors	Repair or replace doors	n/a [		Yes	7		\$ 2,600.00
	Repair or repl. locks/latches	n/a [		Yes	7	Self Help	\$ 600.00
Walls/Ceiling	Repair or repl. @ defective	n/a [		Yes	7		\$ 5,500.00
Paint	Repair or repl. @ defective	n/a [		Yes	7		\$ 3,000.00
Fire Safety							
•	Install smoke/CO alarm:bsmt.	n/a		Yes	<b>~</b>	Self Help	\$ 55.00
	Install smoke/CO alarm: 1st flr.	n/a		Yes	<b>4</b>	Self Help	\$ 165.00
	Install smoke/CO alarm: 2nd flr.	n/a		Yes	<b>4</b>	Self Help	\$ 165.00
Handrails	Repair/replace defective	n/a [	<b>7</b>	Yes		Self Help	\$ 490.00
Stairs	Repair defective	n/a [		Yes	7		\$ 5,200.00
Floors	Repair defective	n/a [		Yes	<b>4</b>		\$ 4,800.00
Other		n/a [		Yes	<b>✓</b>	fireplace	\$ 1,400.00
		n/a [		Yes	<b>V</b>	asbestos removal @ basement mechanicals	\$ 4,000.00
		n/a		Yes			\$
		n/a [		Yes			\$
						Interior: Estimated Cost:	\$ 55,354.00
						Total Exterior and Interior Cost:*	\$ 111,752.00

Inspected by: Tom Frank Date: 8/28/14

## **Self Help**

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.

average contracted cost. Actual costs may vary. Self help will reduce the amount.